

FIG. 1





FIG. 2



```
<deviceAlert3051>  
<date> 09/29/00 </date>  
<time> 02:11:15 PM </time>  
<tag> FT-100 </tag>  
<alert> MAINTENANCE </alert>  
<description> Sensor Plugged </description>  
<priority> 4 </priority>  
<action> Remove and repair </action>  
<state> act/unack </state>  
</deviceAlert3051>
```

} XML

FIG. 4

099022201 071001




FIG. 5




FIG. 6